

Thu, May 3, 2018 2:28 AM

S.S.

From: Michael Wolf <disperser.wolf@mail.ru>

To: pedro@clubcantamar.com



---

FYI, the fueling of Southern Sport has left a significant amount of diesel in the water. I have never seen a spill this bad here - visible slicks of obvious oil. It is quite visible across the entire marina four hours after fueling, and the tide starts coming back in in only two hours. I expect the spill will be very visible in the morning.